Recommended Improvements	Progress to Date
Capital Racquet & Fitness Center	
-Second floor accessibility and fire protection upgrades	Refinished group exercise room floor in 2015 New locker improvements in 2014; hot tub retile
-Locker room renovations	project in 2016 Locker room fans installed 2015; ceiling grid/panel
-Gymnastics and/or tennis expansion	replacement in 2016 Accessible grab bars in women's shower area installed
-Fitness area and administrative office expansion	2015 Replace carpet in main level and locker rooms in
-Entrance renovation	2015; Security cameras installed in 2016
-Address lack of adequate parking	Replaced concrete at gymnastic entrance in 2015
World War Memorial Building	
 Update facilities to improve accessibility, update restroom and athletic facilities, HVAC systems and improve the overall aesthetics. 	2015 improvements: electrical panel upgrades; New floor installed in the main and lower gyms; Plaster repairs and painting on main level; New floor in the main level restrooms
 Option B provided a new use for the south side of the building for the arts, opened up to the Belle Mehus. 	2016 improvements: Electrical upgrades; plaster repair; Painted archery room; Security cameras; Room drain repair; Boiler repairs
Ice Arenas	
 Need for updated/ expanded locker room and lobby spaces and infrastructure upgrades More year-round activities and more programs Due to programs already at capacity, the consultant recommended the following: 	Security cameras installed in both lobbies in 2016; Schaumberg 2014 improvements included paint, locker room, and infrastructure upgrades
-BPRD build one new ice sheet onto an existing ice arena.	The project to add a new sheet of ice and reconfigure Schaumberg Arena is ongoing and will be completed in 2017.
-Update/expand VFW Sport Center rink, lockers rooms, concessions, multi-use space and seating.	Plans in place to remove and replace the floors and compressors in Rink #1 and the curling rink in 2017.
Hillside Pool	
 Replace the aging pool with a new aquatic system with additional water features Renovation the bath house building for accessibility and increased programming and uses, including acting as a community center for the neighborhood. 	New pool and redeveloped bath house building were completed in 2015; Security cameras installed in 2016; Window shades installed 2016.
BSC Aquatic and Wellness Center -New entry/reception lobby -New gymnasium space -Addition group fitness studios -Larger indoor play area -Indoor running/walking track	Security cameras installed in 2016.